



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Date: August 21, 2008

Reviewed: 2/2

Mine Name: RLR Site #6	Permit Number: S0470096
Operator Name: Red Leaf Resources, inc.	Inspection Date: 08/19/2008
Inspector(s): Brett Gregory (for Leslie Heppler)	Time: 2:00 pm
Other Participants: None	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$22,300 **Permit fee:** is current

Purpose of Inspection: This was a first inspection of the site, routine annual inspection. No mining has commenced as of yet.

Inspection Summary: see attached photos

- The road access to the site is behind and directly south of the sign at the junction. I walked a little further south to get to the proposed drilling area.

Conclusions and Recommendations: Nothing to note of any significance. DOGM to continue to monitor this site.

Inspector's Signature

LAH:BG:pb

cc: Red Leaf Resources, Inc. - James Patten
(SITLA - John Blake)


O:\M047-Utah\S0470096-RLR6\inspections\insp-08192008_S0470096.doc



Road behind sign.



Access gate.



Road.



Proposed drilling site.